

000000  
(000000)

[Program Name : ClipInsertion]


[Section Name : Inputs]

Generate signal when all parts are present



000001  
(000003)

Generate signal when all part sensors are off



Title	Clip Insertion Sample Program	Author	A. Zeeman	Step Number	
Number		Revision	1	Date	5/2/2010
					000000